
USB stamp
uC stamp
reset
USB
5Vdc
0.5 mA
(top)
~ your circuit here ~
PWR
GND